




TECHNICAL INFORMATION

Vehicle Speed Sensor Positioning in Dash Cluster



Be sure that the VSS pickup is positioned as shown. When inserting the speedometer cable end, push into the receptacle until the latch snaps as shown and be sure the square drive shaft is engaging into the vehicle odometer assembly. If there is still no VSS code, check the 20 amp GAGES fuse. Also, be sure to check both connectors on the green VSS buffer module, located to the right of the steering column.